

Installation Instructions

1998-2007 DODGE 5.9L CUMMINS (24-VALVE) ISB PICKUP TRUCKS

THIS IS FOR USE WITH SYSTEM 42732

Removal of intake elbow and stock air intake heater.

1. Loosen the clamps that hold the rubber hose at the inlet of the stock intake elbow and slide the hose free of the intake inlet.

Caution: Cover the intercooler up-pipe opening with a clean rag to prevent foreign objects from entering the intake tract.

- **2.** Remove the bolt that holds the dipstick on the intake elbow. Save the bolt for reuse. Gently push and move the dipstick and its holder to the rear of the engine compartment to gain access to the engine.
- **3.** Unbolt and remove the intake elbow from the engine, being careful to not knock any debris into the intake through the electric heater element block.
- **4.** Follow the factory intake heater power cable(s) back to the intake heater relay(s) located on the side of the passenger side battery. Disconnect intake heater power cable(s) from intake heater relay(s).
- **5.** Remove the wires connecting the electric heater element block to the engine and remove the heater element block. Save the fasteners for re-use. Caution: Cover the opening in the intake manifold with a clean rag to prevent foreign objects
- **6.** Being careful not to scratch or gouge the mating surfaces of the parts, completely remove the stock gaskets from both sides of the heater element block and intake manifold, using a gasket scraper as needed. Clean and dry all sealing surfaces thoroughly.
- 7. Install Banks Heater Delete Spacer (42709) using supplied gaskets.
- **8.** Reinstall intake elbow.

Notes: This product is intended for use in warm climates. Engine start-up can be difficult in cold climates. Check engine light's (CEL's) can occur if temperature is too cold during start-up. If CEL's occur reinstall stock air intake heater.

© 2009 GALE BANKS ENGINEERING 546 DUGGAN AVENUE, AZUSA, CA 91702 (626) 969-9600 • FAX (626) 334-1743

PRODUCT INFORMATION & SALES: (800) 438-7693

www.bankspower.com

08/25/09 96426 V.1.0